



READ ME!

When you are installing a Graphtec scanner, it helps to load paper into the scanner. This keeps the scanner from going to sleep.

For the CS1000, CS1100 and CS2000 scanners: See instructions at the bottom of this document.

All of the folders named “User Guide...” are the user guides for the model of scanner named.

Driver v2.2 (32bit):

32bit Windows XP, Vista, 7 and 8 USB driver for **all scanner models except the SK280, CS1000, CS1100 and CS2000.**

To install: run DPInst with the scanner turned off or unplugged from the PC. See *How to install USB driver.pdf* for more detailed information.

Driver v2.2 (64bit):

64bit Windows XP, Vista, 7 and 8 USB driver for **all scanner models except the SK280, CS1000, CS1100 and CS2000.**

To install: run DPInst with the scanner turned off or unplugged from the PC. See *How to install USB driver.pdf* for more detailed information.

Driver (SK280 only, 32bit):

32bit Windows XP, Vista and 7 USB driver **for the SK280 scanner only.**

To install: run DPInst with the scanner turned off or unplugged from the PC. See *How to install USB driver.pdf* for more detailed information.

Driver (SK280 only, 64bit):

64bit Windows XP, Vista and 7 USB driver **for the SK280 scanner only.**

To install: run DPInst with the scanner turned off or unplugged from the PC. See *How to install USB driver.pdf* for more detailed information.

Network Utility v260:

Network Connection Utility installation program for 32bit & 64bit Windows XP, Vista, 7 and 8. Supports all Graphtec scanners with a network connection. Note that CS300 and CS400 scanners are not supported in Windows 8.

Scanning Arts2 v340:

Scanning Arts2 scanning application installation program for 32bit & 64bit Windows XP, Vista, 7 and 8. **Does not work with SK280, CS1000, CS2000, CS300 and CS400.**

Scanning Master v632:

Scanning Master scanning and calibration application installation program. Works on 32bit Windows XP. **Only for CS1000, CS1100 and CS2000.**

Scanning Master v680:

Scanning Master scanning and calibration application installation program. Works on 64bit & 32bit Windows XP, Vista, 7 and 8. **Does not work with CS1000, CS1100, CS2000, CSX510, CSX530, CSX550.**

Note that when Scanning Master is installed, the Scanner Adjustment program for calibrating the scanner is also installed.

For CS1000, CS1100 and CS2000: Use **Scanning Master v632**

For CSX510, CSX530 and CSX550: Use **ScanningMaster Pro Color v700**

For SK280: Install **Scanning Master v680**; then follow instructions in *Installing the SM21+ Software for the SK280 Scanner.pdf*.

SK280 Scanner Adjustment Setup:

SK280 Calibration application installation program. **Works only with SK280.**

TWAIN (SK280, 32bit):

TWAIN installation program for 32bit operating systems **for the SK280 only.**

TWAIN v700:

TWAIN installation program for 32bit & 64bit Windows XP, Vista and 7. **For all scanner models except SK280, CS1000, CS1100 and CS2000.**

TWAIN v830:

TWAIN installation program for 32bit & 64bit Windows XP, Vista, 7 and 8. For all scanner models except SK280, CS1000, CS1100, CS2000, CS300, CS400 and 42" scanners without network connection.

ScanningMaster Pro Color v700:

Scanning Master Pro color software for CSX510, CSX530 and CSX550 scanners. Works with Windows XP, Vista and 7. Regular installation.

ScanningMaster Pro Color v830up:

Scanning Master Pro color software for CSX510, CSX530 and CSX550 scanners. Works with Windows XP, Vista, 7 and 8. Upgrade installer, requires that an earlier version is already installed on the PC. Install **ScanningMaster Pro Color v700** first.

Installing the CS1000, CS1100 and CS2000:

1. There is no Windows driver for these SCSI scanners.
2. Install the SCSI card and its Windows driver.
3. Connect the scanner to the SCSI card. Turn on the scanner and then the PC.

4. The SCSI card should see the scanner and the scanner should show up in Device Manager. The scanner will have no driver installed.
5. Go to www.adaptec.com. Search for *Windows ASPI Package*. Download and run the executable file.
6. Go to *C:\adaptec\aspi* and run *aspiinst.exe*. Reboot the PC.
7. Install Scanning Master v632 from this download.
8. Launch Scanning Master.
9. Go to the Scan pull down menu and select Model Setup.
10. Select your model. Click the Confirm button to confirm that you have communication.